# Frank's Collision Repair 5703 Southampton Drive Murphy , TX 75081 1-8585478697

09/17/2020, 02:53 PM

## **TEST DRIVE COPILOT DRIVE REPORT**

RO Number: 098775542 Invoice Number: 7952

Year: 2019 Insurance: Allied

Make: Cadillac Model: CT6

VIN: 8273748484848TEST

Road Test Type: Collision Repair, ADAS

**Technicians:** Tommy Test Drive

Start Time:02:53 PMStart Mileage:24,885.0 milesEnd Time:03:01 PMEnd Mileage:24,888.2 milesTotal Time:0.13 hrsTotal Mileage:3.2 miles


**Highest Speed:** 66.0 mph **Weather:** 

**Lowest Speed:** 1.0 mph **Average Speed:** 33.5 mph


Video Link: https://testdriveshop48.s3.us-west-1.wasabisys.com/098775542-2019-Cadillac-CT6-9-

17-2020-2-53.mp4

#### Test Drive Speed (this represents the vehicle's speed during the actual test drive):



### Test Drive Map (this represents drive path taken during the actual test drive):



### **Final Test Drive Checklist**

The person performing the test drive on this vehicle has validated the following systems:

Passed System operates as designed.

Failed System DID NOT operate as designed.N/A System is not available on this vehicle.

| Adaptive Cruise Control      |                   | <b>✓</b> | Passed  Faile | ed 🗌 N/A |
|------------------------------|-------------------|----------|---------------|----------|
| Front Automated Braking      |                   | <b>✓</b> | Passed  Faile | ed 🗌 N/A |
| Rear Automated Braking       |                   | <b>✓</b> | Passed  Faile | ed 🗌 N/A |
| Lane Departure Warning       |                   | <b>✓</b> | Passed  Faile | ed 🗌 N/A |
| Lane Keep Assist             |                   | <b>✓</b> | Passed  Faile | ed 🗌 N/A |
| Following Distance Indicator |                   | <b>✓</b> | Passed  Faile | ed 🗌 N/A |
| Forward Collision Alert      |                   | <b>✓</b> | Passed  Faile | ed 🗌 N/A |
| Page 2 of 3                  | Test Drive Report |          |               |          |

| Blind Zone Alert                                  | <b>✓</b> | Passed  Failed  N/A   |
|---|----------|-----------------------|
| Rear Camera Mirror                                | <b>✓</b> | Passed ☐ Failed ☐ N/A |
| Rear Cross Traffic Alert                          | <b>✓</b> | Passed ☐ Failed ☐ N/A |
| Automatic Park Assist                             | <b>✓</b> | Passed ☐ Failed ☐ N/A |
| Front and Rear Park Assist                        | <b>✓</b> | Passed ☐ Failed ☐ N/A |
| Pedestrian Detection and Front Braking Technology | <b>✓</b> | Passed ☐ Failed ☐ N/A |
| Rear Park Assist                                  | <b>✓</b> | Passed ☐ Failed ☐ N/A |
| Front Curb View Camera                            | <b>✓</b> | Passed ☐ Failed ☐ N/A |
| Rear Camera Mirror Washer                         | <b>✓</b> | Passed ☐ Failed ☐ N/A |
| Night Vision                                      | <b>V</b> | Passed ☐ Failed ☐ N/A |